



Inspection Detail



Client:	HDD Broker		
Inspected by:			
Location of Inspection:			
Phone No / Email:			
Date of Inspection:	8/20/2025	Job#:	
Year:	2019	Make:	VM
Model:	D20X22III	VIN/SN:	

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Inspection Details					
Unit Information					
Hours:	2,892	Date:	N/A		
General Body					
Paint condition:	See Notes	Panel dents:	Yes	Corrosion:	No
Dents/Bends:	No	Visible leaks:	No	Operator console pivot/lock:	No Damages Observed
Operator's Seat:	No Damages Observed	Operator Console Joysticks, switches, gauges:	See Notes	Fresh water tank (if applicable):	No Damages Observed
Safety Equipment					
Operator's presence switch (seat):	No Damaged Observed	Safety switches:	No Damages Observed	Red safety bars (rod loader extensions):	No Damages Observed
Work lights:	No Damages Observed	Strike alert/ground wire:	No Damages Observed	Safety decals:	See Notes
Breakout System					
Breakout jaw wear:	See Notes	Cylinder and hose condition:	No Damages Observed	Pins/bushings slop:	No Damages Observed
Front Stakedown System:	No Damages Observed	Auger condition:	No Damages Observed		
Main Drive System					
Tracks (steel or rubber):	Rubber	Track condition:	See Notes	Sprockets/rollers:	No Damages Observed
Rear Outriggers					
Cylinder and hose condition:	No Damages Observed	Pins and bushings:	No Damages Observed	Bent/broken parts:	No
Carriage					
Wear pads/carriage slop:	No Damages Observed	Motors and hoses condition:	See Notes	Rack and pinion condition:	No Damages Observed
Engine Details					
Fluid level and condition:	Low Level/ Good Color	Visible leaks:	No	Belts and pulleys:	No Damages Observed
Engine mounts:	No Damages Observed	Radiator/hoses:	No Damages Observed		
Operation					
Engine start and idle:	No	Engine smoke:	No	Engine noises (tick/knock):	No
Rear outrigger operation:	No Damages Observed	Main rack tilt:	No Damages Observed	Front stakedown rotation/up/down:	No Damages Observed
Breakout vices open/close/rotate:	No Damages Observed	Rod loader lift/shuttle/alignment:	No Damages Observed	Carriage traverse (thrust/pullback):	No Damages Observed
Rotation motor fwd/reverse:	No Damages Observed	Mud pump on/off:	No Damages Observed		
Drill Rods					
Rod count:	40	Bent rods:	No	Thread condition:	No Damages Observed
Corrosion:	No				

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tracks					
Left Track Condition:	See Notes	Left Tire Brand:	Obstructed	Left Tire Size:	Obstructed
LeftTrack Tread Depth Measurement:	1”	Left Track Rollers:	See Notes		
Right Track Condition:	See Notes	Right Tire Brand:	Obstructed	Right Tire Size:	Obstructed
RightTrack Tread Depth Measurement:	24/32”	Right Track Rollers:	No Damages Observed		
Observations / Comments					
The unit starts and operates.					

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



Wear and Tear Items

Item Name	Item Comments
Breakout Jaw	Based on the operational video, the breakout jaw appears to be sticking.
Drill Frame	The drill frame is dented.
Plastic Tape	The sheet metal panel near the engine compartment has plastic tape or covering on it, indicating possible previous damage to the panel.
Rollers Frame	The left roller frame is rusty and needs to be painted.
Right Track	The right track is worn, has a chunk of rubber coming off, and has small gouges.
Left Track	The track is worn and has small cracks.
Hydraulic Insulation	The hydraulic insulation is damaged.
Hydraulic Oil	The hydraulic visor indicates a low hydraulic oil level.
Decals	There are damaged sticker decals around the unit.
Joystick Plate & Frame	The joystick switch cover is damaged and the covers are faded.
Joystick Plate & Frame	The plate is cracked and the frame paint is damaged.
Joystick Rubber Boot	The rubber is torn.
Dashboard Paint	The dashboard paint is peeling and scratched.
Warning Light	There is a warning light on the dashboard.
Side Panel Sheet	The side panel is dented.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.