



CONDITION REPORT

TRENCHLESS EQUIPMENT

MAKE:

Vermeer

MODEL:

Navigator D33X44

SERIAL:

HOURS:

YEAR:

2006

CUSTOMER:

CONTACT:

PHONE #

EVALUATOR:

DATE:

12/11/23

GENERAL OVERALL CONDITION

(Higher Numbers are Better)

1 2 3 4 5

☐ ☐ ☐ ☒ ☐

INSPECTION RATINGS KEY

- 5 = Excellent cond.-New or recently replaced parts.
4 = Operates well, shows less than average wear.
3 = Operates and is in avg. condition for age and hrs, minimal repairs.
2 = Operates but needs repairs.
1 = Repairs necessary prior to use.

DIRECTIONS / CUSTOMER INFO.

ENGINE

(Higher Numbers are Better)

1 2 3 4 5 N/A

Fluid level and condition	☐ 1/4	☐ 1/2	☐ 3/4	☒ Full	
Perform Oil Sample	☐ YES			☒ NO	
Engine Noise	☐ YES			☒ NO	☐
Engine Smoke	☐ YES			☒ NO	☐
Visible Leaks	☐ YES			☒ NO	☐
Gauges Instruments	☐	☐	☐	☐	☒
Belts and Pulleys	☐	☐	☐	☐	☒
Idle and Throttle Quality	☐	☐	☐	☐	☒
Engine Mounts and Slides	☐	☐	☐	☐	☒
Radiator / Hoses	☐	☐	☐	☐	☒
Any Missing Parts	☐ YES			☒ NO	

NOTES

Engine Rebuilt
In great working
shape

SAFETY EQUIPMENT

(Higher Numbers are Better)

1 2 3 4 5 N/A

Seat Belt	☒ YES			☐ NO	☐
Operator Presence Switch (seat)	☒ YES			☐ NO	☐
Safety Switches	☒	☐	☐	☐	☐
Red Safety Bars/ E- stops	☒	☐	☐	☐	☐
Work Lights	☒ YES			☐ NO	☐
Strike Alert / Ground wire	☒	☐	☐	☐	☐
Decals In Place / Legible	☒ YES			☐ NO	☐
Any Missing Parts	☐ YES			☒ NO	☐

All present &
works as should

BODY PANELS

(Higher Numbers are Better)	1	2	3	4	5	N/A
Paint	☐	☐	☐	☒	☐	
Panel Dents		☐ YES		☒ NO		
Rust		☐ YES		☒ NO		
Frame	☐	☐	☐	☒	☐	
Any Missing Parts		☐ YES		☒ NO		

All in good condition

OPERATION FUNCTION

(Higher Numbers are Better)	1	2	3	4	5	N/A
Gearbox Rotation at Full RPM	☐	☐	☐	☒	☐	
Rollers	☐	☐	☐	☒	☐	
Drilling Fluid Shutoff Ball Valve	☐	☐	☐	☒	☐	
Throttle Control Front & Rear	☐	☐	☐	☒	☐	
Front Vice	☐	☐	☐	☒	☐	
Front Vice Cylinder Pins & Frame	☐	☐	☐	☒	☐	
Rear Vice	☐	☐	☐	☒	☐	
Rear Vice Cylinder Pins & Frame	☐	☐	☐	☒	☐	
Rear Vice Tilt	☐	☐	☐	☒	☐	
Vice Jaws Damage And Wear		☐ YES		☒ NO		
Rear Tilt Cylinder	☐	☐	☐	☒	☐	
Right Stake down Up/Down+ Rotation	☐	☐	☐	☒	☐	
Rotation	☐	☐	☐	☒	☐	
Pins & O rings	☐	☐	☐	☒	☐	
Left Stake down Up/Down+ Rotation	☐	☐	☐	☒	☐	
Rotation	☐	☐	☐	☒	☐	
Pins & O rings	☐	☐	☐	☒	☐	
Console Pivots	☐	☐	☐	☒	☒	
Rotation Lever, Self Center		☒ YES		☐ NO		
Thrust Lever, Self Center Thrust		☒ YES		☐ NO		
Rod Loader Arms In/Out		☒ YES		☐ NO		
Water Pump On/OFF		☒ YES		☐ NO		
Water Pump GPM Up/Down						
Chain & Chain Pins	☐	☐	☐	☒	☐	
Chain Adjustment	☐	☐	☐	☒	☐	
Wear Pads (Drive Chuck)	☐	☐	☐	☒	☐	
Rack And Pinion	☐	☐	☐	☒	☐	
Pinion Gears	☐	☐	☐	☒	☐	
Any Missing Parts		☐ YES		☒ NO		

All work as shald



TRACKS AND FRAME

(Higher Numbers are Better)	1	2	3	4	5	N/A
Right Track Forward/Reverse	☐	☐	☐	☒	☐	☐
Track Chain Rollers	☐	☐	☐	☒	☐	☐
Check Track Sprockets	☐	☐	☐	☒	☐	☐
Left Track Forward/Reverse	☐	☐	☐	☒	☐	☐
Track Chain Rollers	☐	☐	☐	☒	☐	☐
Check Track Sprockets	☐	☐	☐	☒	☐	☐
Rollers	☐	☐	☐	☒	☐	☐
Rubber Pads	☐	☐	☐	☒	☐	☐
Track Adjustment	☐	☐	☐	☒	☐	☐
Rear Outrigger Up/Down	☐	☐	☐	☒	☐	☐
Track Extension	☐	☐	☐	☒	☐	☐
Tilt Pivot	☐	☐	☐	☒	☐	☐
Tilt Cylinder	☐	☐	☐	☒	☐	☐
Track Condition	☐	☐	☐	☒	☐	☐
Any Missing Parts	☐ YES			☒ NO		

All works as
should

UNDER CARRIAGE

(Higher Numbers are Better)	1	2	3	4	5	N/A
Track Frame Cracks, Repairs	☐ YES			☒ NO		☐
Rollers / Idlers	☐	☐	☐	☒	☒	☐
Sprockets	☐	☐	☐	☐	☒	☐
Any Missing Parts	☐ YES			☒ NO		

New sprockets

ROD AND ROD BOX

(Higher Numbers are Better)	1	2	3	4	5	N/A
Number Of Rods / Size	Number of Rods: 48					Size: N/A
Check For Wear %	10/new%					
Bent Rods #	0					
Check Threads W/gauge	☐ YES			☒ NO		
Check Shoulders W /gauge	☐ YES			☒ NO		
Rod Wipers / Holder Damage	☐	☐	☐	☐	☐	☒
Rod Box	☐	☐	☐	☒	☐	☐
Top Pins / Bottom Pins	☐	☐	☐	☒	☐	☐
Rod Box Damage	☐	☐	☐	☐	☒	☐
Rod Box Cover	☐	☐	☐	☐	☒	☐
Any Missing Parts	☐ YES			☒ NO		

Size: N/A

NO Bent Rods

we have extra rods
for sale

Rods work as should
Qty 48 2-3/8" FS 2 x 15'
drill pipe
Qty 48 of these

TOOLING / LOCATOR

(Higher Numbers are Better)	1	2	3	4	5	N/A
Drill Head	☐ YES			☒ NO		☐
Starter Rod	☐ YES			☒ NO		☐
Hex Collar	☐ YES			☒ NO		☐
Duck Bills	☐ YES			☒ NO		☐
Reamers	☐ YES			☒ NO		☐
Reamer Sizes	inches					
Wash Wand	☐	☐	☐	☐	☐	☒
Locator	☐	☐	☐	☐	☐	☒
Remote	☐	☐	☐	☐	☐	☒
Probes Color	☐	☐	☐	☐	☐	☒
Probes Heat Indicator	☐	☐	☐	☐	☐	☒
Cones	☐	☐	☐	☐	☐	☒

was back-up
machine
still has 75-80% life remaining

SN#

SN#

SN#

CAB

(Higher Numbers are Better)	1	2	3	4	5	N/A
A/C	☐ YES			☒ NO		☐
Heater	☐ YES			☒ NO		☐
Glass	☐	☐	☐	☒	☐	☐
Wipers	☐	☐	☐	☒	☐	☐
Doors	☐	☐	☐	☒	☐	☐
Multi-Function Display	☐	☐	☐	☒	☐	☐

HYDRAULIC SYSTEM

(Higher Numbers are Better)	1	2	3	4	5	N/A
Hydraulic Fluid Condition	☐ 1/4	☐ 1/2	☐ 3/4	☒ Full		
Pump Pressure / Flow	N/A PSI.					
Visible Leaks	☐ YES			☒ NO		☐
Hoses and Fittings	☐	☐	☐	☐	☒	☐
Operation of Controls	☐	☐	☐	☐	☒	☐
Hydraulic Tank and Caps	☐	☐	☐	☐	☒	☐
Perform Oil Sample	☐ YES			☒ NO		

work as should

Salesman:

PICTURES

☒ YES ☐ NO

NOTES

Machine was used as a back-up.
still has 75%-80% life remaining.

MIXING SYSTEM

SERIAL:

MODEL:

NOTES

ENGINE

(Higher Numbers are Better)	1	2	3	4	5	N/A
Fluid level and condition	☐ 1/4	☐ 1/2	☐ 3/4	☒ Full		
Engine Noise	☐ YES		☒ NO			
Engine Smoke	☐ YES		☒ NO			
Visible Leaks	☐ YES		☒ NO			
Idle and Throttle Quality	☐	☐	☐	☐	☒	
Engine Mounts	☒ YES		☐ NO			
Any Missing Parts	☐ YES		☒ NO			

work as should

TANK

(Higher Numbers are Better)	1	2	3	4	5	N/A
Condition of Tank	☐	☐	☐	☐	☐	☒
Hoses	☐	☐	☐	☐	☐	☒
Caps	☐	☐	☐	☐	☐	☒
Ball Valves	☐	☐	☐	☐	☐	☒
Hopper	☐	☐	☐	☐	☐	☒
Any Missing Parts	☐ YES		☐ NO			

N/A

PUMP

(Higher Numbers are Better)	1	2	3	4	5	N/A
Condition of Pump	☐	☐	☐	☒	☐	
Pump Noise	☐ YES		☒ NO			
Visible Leaks	☐ YES		☒ NO			
Packings	☐	☐	☐	☐	☐	
Any Missing Parts	☐ YES		☐ NO			

All as should be

TRUCK

SERIAL:

MODEL:

MILAGE:

(Higher Numbers are Better)	1	2	3	4	5	N/A
Cab and Body	☐	☐	☐	☐	☐	☒
Paint	☐	☐	☐	☐	☐	☒
Panel Dents	☐ YES		☐ NO			☒
Rust	☐ YES		☐ NO			☒
Any Missing Parts	☐ YES		☐ NO			

TRAILER

SERIAL:

MODEL:

(Higher Numbers are Better)	1	2	3	4	5	N/A
Paint / Rust	☐ YES		☐ NO			☒
Damage	☐	☐	☐	☐	☐	☒
Tires	☐	☐	☐	☐	☐	☒
Lights	☐ YES		☐ NO			☒
Brakes	☐	☐	☐	☐	☐	☒

This inspection report has been furnished solely for informational purposes and it is not to be construed in any way as a warranty or guarantee on the condition of the equipment. Buyers should confirm the accuracy of this report to their satisfaction prior to purchase. Buyer agrees to hold harmless HDD Broker, the seller and the inspecting agent.