MIXING SYST	EM						
SERIAL:					M	IODEL:	1999 VERMEER ST500 Mud Mixing System/ Honda pump
ENGINE				"		NOTES	
(Higher Numbers are Better)	1	2	3	4	5	N/A	
Fluid level and condition	□1/2		½ □]¾ x]Full			
Engine Noise	□ YES			[x] NO			
Engine Smoke	☐ YES			[x] NO			
Visible Leaks	☐ YES			□ NO			
Idle and Throttle Quality					[x]		
Engine Mounts	[>	YE	S		C		
Any Missing Parts	[□ YE	S	[x] N	0		
TANK							
(Higher Numbers are Better)	1	2	3	4	5	N/A	
Condition of Tank				[x			
Hoses				[x			
Caps				x]			
Ball Valves				[x]			
Hopper				[x]			
Any Missing Parts	[□ YE	S	[x NO			
PUMP							
(Higher Numbers are Better)	1	2	3	4	5	N/A	
Condition of Pump					[x]		
Pump Noise	☐ YES			[x] NO			
Visible Leaks	☐ YES			x NO			
Packings							
Any Missing Parts		YES	3	x] NC)		

							_		
	TRAILER								
SERIAL:						N	10DEL:	H524	2 YEAR: 2021 PJ TRAILER
	(Higher Numbers are Better)	1	2	3	4	5	N/A		
Paint / Rust		□ YES		[x] NO			_	Tires in good condition and new spare tire	
Damage							[x]		
Tires									
Lights		[2	x) YES	3					
Brakes						[x			

This inspection report has been furnished solely for informational purposes and it is not to be construed in any way as a warranty or guarantee on the condition of the equipment. Buyers should confirm the accuracy of this report to their satisfaction prior to purchase. Buyer agrees to hold harmless HDD Broker, the seller and the inspecting agent.